
VPI P/N: FIBER-D-LC-WTP-CB


Assembly Instruction Field Serviceable/Installable





Follow the order from 4 to 1 and put components through cable accordingly, no need to assemble here.





Then assemble $3 \rightarrow 1$, $4 \rightarrow 1$) and follow the torque force accordingly.

